

INDIANA THEATRE FACILITY ASSESSMENT

TERRE HAUTE, INDIANA • JULY 24, 2024



CONTENTS

1 INFORMATION GATHERING

HISTORIC RESEARCH
ON-SITE OBSERVATION
LIDAR SCANNING + DIGITAL MODELING
STAKEHOLDER MEETINGS

2 PROGRAMMING + PROJECT DEFINITION

PROGRAMMING
PATRON AMENITIES
PERFORMER AMENITIES
PRODUCTION
BUILDING CHALLENGES

3 ASSESSMENT REPORT + CONCEPTUAL DESIGN

RENOVATED PLANS
MECH., ELEC., + PLUMBING
BUDGET



1 INFORMATION GATHERING








HISTORIC RESEARCH




STAKEHOLDER MEETINGS



LIDAR SCANNING + DIGITAL MODELING






ON-SITE OBSERVATION

PROGRAMMING + PROJECT DEFINITION

THE FOUR P'S: **PROGRAMMING**



EXISTING AUDITORIUM

STAKEHOLDER IDEAS:

- MOVIES
- . THEATRE
- . COMMERCIAL CONCERTS
- ORCHESTRA CONCERTS
- . COMEDY
- . LECTURE
- . DANCE
- . KID'S PROGRAM
- . HISTORICAL TOURS
- . CONVENTION CENTER EVENTS
- . RENTALS
- WEDDINGS
- . UNIVERSITY & SCHOOL USE
- . CORPORATE EVENTS
- . CHURCH EVENTS




ORCHESTRA



MUSICAL THEATRE

PROGRAMMING + PROJECT DEFINITION

THE FOUR P'S: **PROGRAMMING**



EXISTING AUDITORIUM

STAKEHOLDER IDEAS:

- . MOVIES
- . THEATRE
- . COMMERCIAL CONCERTS
- ORCHESTRA CONCERTS
- . COMEDY
- . LECTURE
- . DANCE
- . KID'S PROGRAM
- . HISTORICAL TOURS
- . CONVENTION CENTER EVENTS
- . RENTALS
- WEDDINGS
- . UNIVERSITY & SCHOOL USE
- . CORPORATE EVENTS
- . CHURCH EVENTS



ORCHESTRA



MUSICAL THEATRE

2 PROGRAMMING + PROJECT DEFINITION

THE FOUR P'S: PATRON AMENITIES



CROWD DENSITY EXAMPLE: 7 SQUARE FEET / PERSON

CURRENT CONDITIONS ARE LACKING SEVERAL AMENITIES:

- . DROP-OFF ZONE
- FOOD & BEVERAGE
- . ACCESSIBLE RESTROOMS
- . ADEQUATE SEATING
- . BOX OFFICE
- . LIGHTING
- PARKING

RECOMMENDATIONS:

- DROP-OF ZONE
- . FOOD & BEVERAGE
- NEW RESTROOMS
- . UPGRADED SEATING
- EXPANDED LOBBY (8 FT²/PERSON)
- BOX OFFICE
- . UPGRADED LIGHTING
- ROOF REPAIR & PLASTER RESTORATION
- PARKING



RESTROOMS




FOOD & BEVERAGE



AUDITORIUM SEATING

PROGRAMMING + PROJECT DEFINITION

THE FOUR P'S: PERFORMER AMENITIES



EXISTING DRESSING ROOM WITH BATHROOM

CURRENT CONDITIONS NEED UPDATING:

- DRESSING ROOMS & GREEN ROOM IN BASEMENT
- DRESSING ROOMS ON GALLERY LEVEL STAGE LEFT

RECOMMENDATIONS

- RECONFIGURE BASEMENT DRESSING ROOMS & GREEN ROOM
- RENOVATE GALLERY LEVEL DRESSING ROOMS
- EXPAND & RENOVATE GREEN ROOM
- . BASEMENT LEVEL PIANO STORAGE
- BASEMENT LEVEL WARDROBE & LAUNDRY



GREEN ROOM




DRESSING ROOM



DRESSING ROOM

PROGRAMMING + PROJECT DEFINITION

THE FOUR P'S: **PRODUCTION**



EXISTING GRID ABOVE STAGE

CURRENT CONDITIONS LACK SEVERAL SPACES & SYSTEMS:

- PRODUCTION OFFICES
- . CREW SUPPORT SPACES
- . LOADING CAPABILITIES
- . TECHNICAL SYSTEMS

RECOMMENDATIONS

- PRODUCTION OFFICES
- . PRODUCTION RIGGING
- ORCHESTRA LIFT
- . LOADING DOCK
- . PRODUCTION POWER
- . HOUSE SYSTEMS
- . LIGHTING
- . AUDIO-VISUAL SYSTEMS



RIGGING



FOLLOW-SPOTS & PROJECTION





HOUSE SYSTEMS

2 PROGRAMMING + PROJECT DEFINITION

THE FOUR P'S:


- **PROGRAMMING**
- PATRON
- PERFORMER
- PRODUCTION






SECOND FLOOR





FIRST FLOOR





BASEMENT



ARCHITECTURAL ASSESSMENT

LIFE SAFETY:


- INADEQUATE STAIRS
- MULTIPLE EXITS REQUIRED FROM AUDITORIUM, LOBBY, ETC.

ACCESSIBILITY:

- . INACCESSIBLE RESTROOMS
- INSUFFICIENT & INACCESSIBLE AUDITORIUM SEATING

CIRCULATION:

- . DISCONNECTED BASEMENTS
- PATRON AND PRODUCTION DROP-OFF
- . LEVEL CHANGES




EXTERIOR FACADES



CRACKED UNITS



SPALLED UNITS



DISTRESSED PILASTERS
SOUTH FACADE



DETERIORATED / STAINED BRICK



EXPOSED CLAY TILE WEST FACADE



SPALLED CONCRETE LINTELS
+ DOOR FRAMES

PLASTER



PEELING PAINT



CRAZED PAINT



MISSING PLASTER EXPOSED METAL LATH



MISSING PLASTER, EXPOSED LATH, + PEELING PAINT



WATER DAMAGE ON WALL + CEILING



MISSING COATING, MISSING PLASTER, + EXPOSED BRICK BACKUP

ROOFS



CRAZING + EXPOSED REINFORCING



BROKEN / MISSING STAINER DRAINS



CRACKED + MISSING TILES



MISSING GUTTERS + STAINED FACADE




CRACKED, MISSING, OPEN COPINGS



FRIABLE + MISSING SHINGLES

STRUCTURE



CORROSION ON METAL
CONCRETE FORMS



CRACKED BRICK TO PROSCENIUM ARCH



SPALLED CONCRETE + EXPOSED
REINFORCEMENT IN BASEMENT AREAS


FLOOR PLANS:

BASEMENT

- 1 PATRON RESTROOMS
- 2 TABLE + CHAIR STORAGE
- ORESSING ROOMS
- 4 GREEN ROOM
- **5** PERFORMER RESTROOMS
- 6 ELEVATOR
- ORCHESTRA PIT
- 8 LAUNDRY ROOM
- 9 PRODUCTION OFFICES








FLOOR PLANS:

⊕ FIRST FLOOR

- 1 PATRON RESTROOMS
- 2 STAGE
- **3** 1550-SEAT AUDITORIUM
- 4 FOOD + BEVERAGE BAR
- **6** LOBBY
- 6 ELEVATOR
- WARMING KITCHEN
- **8** ORCHESTRA PIT
- INDIANA LANDMARKS
- 10 CONCIERGE
- **1** FRONT-OF-HOUSE OFFICE
- 12 ADA RAMP
- **®** ORCHESTRA SHELL
- MPLOYEE AREA










FLOOR PLANS: SECOND FLOOR

- 1 PATRON RESTROOMS
- 2 STAGE
- 3 1550-SEAT AUDITORIUM
- 4 FOOD + BEVERAGE BAR
- **6** LOBBY
- 6 ELEVATOR
- 7 VIP SEATING
- **8** ORCHESTRA PIT
- 9 INDIANA LANDMARKS
- 10 DRESSING ROOMS
- 1 ORCHESTRA SHELL









ENLARGED FLOOR PLANS: ROOM SETTINGS

- 1 VIP BOOTHS
- 2 ADA VIP OPTION 1
- 3 ADA VIP OPTION 2
- 4 PERFORMANCE SETTING
- **5** BANQUET SETTING



AUDITORIUM FIRST FLOOR SETTING 1



AUDITORIUM FIRST FLOOR SETTING 2







- BANQUET SETTING
- 2 TRAINING SETTING
- 3 FOOD + BEVERAGE












SECOND FLOOR LOBBY SETTING 2

FLOOR PLANS: THIRD FLOOR

- 1 PATRON RESTROOMS
- 2 STAGE RIGGING
- 3 1550-SEAT AUDITORIUM
- 4 CONTROL
- 5 PROJECTION
- 6 ELEVATOR
- **7** VIP SEATING
- 8 INDIANA LANDMARKS









SITE PLAN


- 1 PATRON DROP-OFF ZONE
- PRODUCTION DROP-OFF ZONE
- **3** SHORTENED CROSSWALK
- 4 SIDEWALK BUMPOUT
- 5 EXPANDED CURB CUT
- 6 PATRON ENTRANCE
- STAFF ENTRANCE
- (B) INDIANA LANDMARKS
- 9 ART MUSEUM
- 10 CASA URBANA







MECHANICAL, ELECTRICAL, + PLUMBING



EXISTING HISTORIC SWITCHBOARD

HVAC

- EXISTING: FULL REMOVAL
- NEW: 4-PIPE HEATING + COOLING SYSTEM

PLUMBING

- DOMESTIC WATER: 4" NEW WATER SERVICE
- HOT WATER: ELECTRIC WATER HEATERS
- DOMESTIC WATER SOFTENER: ALL DOMESTIC WATER
- SANITARY WASTE + VENT: FULL REPLACEMENT
- STORM: ROOF + OVERFLOW DRAINS
- NATURAL GAS: LOW PRESSURE GAS SERVICE
- INSULATION: PROVIDED PER CODE + TO PREVENT CONDENSATION
- PIPING SYSTEMS: COPPER, PVC, CAST IRON, + STEEL
- PLUMBING FIXTURES: ALL NEW CHINA + CHROME FIXTURES

FIRE PROTECTION

WET PIPE AUTOMATIC SPRINKLER SYSTEM

ELECTRICAL

- EXISTING: FULL REMOVAL
- NEW: 1000 KVA, 1600 AMP, 277/480-VOLT, 3-PHASE, 4-WIRE

ESTIMATED BUDGET

DESIGN + CONSTRUCTION: \$426.18 X 49,640 FT² = \$21,155,715

EQUIPMENT + SEATING: \$6,200,364

PROJECT TOTAL: \$27,356,079

ITEM	COST
GENERAL REQUIREMENTS	\$1,433,474
SELECTIVE DEMOLITION	\$307,761
CONCRETE	\$351,500
MASONRY	\$650,925
METAL	\$650,400
WOOD, PLASTICS, COMPOSITES	\$139,240
THERMAL + MOISTURE PROTECTION	\$555,420
OPENINGS	\$607,590
FINISHES	\$1,692,451
SPECIALTIES	\$245,000
EQUIPMENT	\$10,000
CONVEYING EQUIPMENT	\$320,000
FIRE PROTECTION	\$367,480
PLUMBING	\$563,600
MECHANICAL	\$4,921,500
ELECTRICAL	\$3,342,300
SITE IMPROVEMENTS	\$35,475
UTILITIES	\$5,000
SUBTOTAL	\$16,199,116
DESIGN CONTINGENCY	\$1,619,912
CONSTRUCTION CONTINGENCY	\$1,619,912
ESCALATION	\$971, 947
CM FEE	\$615,021
PRECONSTRUCTION SERVICES	\$40,000
DESIGN + CONSTRUCTION TOTAL	\$21,155,715
THEATRE EQUIPMENT + SEATING	\$6,200,364
PROJECT TOTAL	\$27,356,079

